## Message

From: Greene, Nikia [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=32A08A414A4F40199B557C0819EB7D0B-GREENE, NIKIA]

**Sent**: 3/15/2019 3:37:25 PM

To: Curt Coover [cooverca@cdmsmith.com]; David Shanight [shanightdt@cdmsmith.com]; Storrar, Chapin S.

[storrarcs@cdmsmith.com]

Subject: FW: Hydrocarbon

FYI

Nikia Greene Remedial Project Manager U.S. EPA, Region 8 (406)-457-5019 greene.nikia@epa.gov

From: Bryson, Josh <josh.bryson@bp.com> Sent: Thursday, March 14, 2019 2:11 PM

To: Greene, Nikia <Greene.Nikia@epa.gov>; Daryl Reed (dreed@mt.gov) <dreed@mt.gov>

Subject: FW: Hydrocarbon

Hi Nikia and Daryl,

Please reference Heather's email below. We've encountered hydrocarbons during our interim "Parrot" sampling effort. Heather has notified the appropriate DEQ agency. We will be collecting some grab samples from the subdrain to assess whether or not we are capturing any HC's.

## Josh Bryson, PE, PMP

Operations Project Manager Remediation Management Services Company An Affiliate of **Atlantic Richfield Company** 

406-723-1834 (Office) 406-565-7164 (Mobile)

From: Heather Brown <a href="mailto:hbrown@pioneer-technical.com">hbrown@pioneer-technical.com</a>

**Sent:** Thursday, March 14, 2019 12:54 PM **To:** Bryson, Josh <<u>josh.bryson@bp.com</u>>

Subject: Hydrocarbon

Hi Josh,

Our field crew encountered a problem while sampling MSD-01A during the monthly monitoring activities under the Parrot Removal Monitoring SAP. I've included a screenshot of the area below. During the February event the team noticed a strong hydrocarbon odor while sampling but when checking the well with the PID and interface they did not detect anything. They also noticed the smell today and picked up a reading of 44.8 ppm from the purge water inside of the tank. The water is being transferred to a barrel to be disposed of at a later date.

I've contacted DEQ Enforcement and notified them of the situation. Please let me know if there is anything else that should be done for the time being.



Pioneur Technical Services Inc. 1101 South Montana Street | Butte, MT 89701 Office: 406.497.8047 | Cell: 406.939.0478





This e-mail and any attachments are intended only for the named recipient(s) and may contain information that is legally privileged, confidential, or exempt from disclosure under applicable law. This message may be logged for archival purposes, may be reviewed by parties at Pioneer Technical Services other than those named in the message header, and may not necessarily constitute an official representation of Pioneer Technical Services. If you have received this message in error, or are not the named recipient(s), you may not retain copy or use this e-mail or any attachment for any purpose or disclose all or any part of the contents to any other person. Any such dissemination, distribution or copying of this e-mail or its attachments is strictly prohibited. Please immediately notify the sender and permanently delete this e-mail and any attachment from your computer. Please do not send any information via e-mail that is subject to relevant export controls, sanction requirements, or that is classified as covered defense information, as that term is defined in DFARS 252.204-7012. Please note that email messages and attachments may be stored or processed on information systems that have not yet been assessed to be compliant with NIST SP 800-171. Accordingly, you are hereby advised not to share any information with Pioneer Technical Services via e-mail that requires NIST SP 800-171 compliant storage or processing. Please contact it@pioneer-technical.com with any questions or concerns.